

Certificate according to EN ISO 3834-2



We confirm that the company

MOS Servis d.o.o.

Mestinje 2B, 3241 Podplat

Unit: MOS Servis d.o.o.

Located in: Mestinje 2B, 3241 Podplat

has proved its ability to fulfill the quality requirements for fusion welding of metallic materials, covered by the ranges described in standard

SIST EN ISO 3834-2:2006

First issue date: 25. 05. 2020

Date of expiry: 25. 05. 2021

Remarks: This certificate remains valid as long as the conditions laid down in the technical specification in reference or the manufacturing conditions in the factory itself are not modified significantly.
The current validity of the certificate can be checked on: info@i-var.si

To this certificate belongs the appendix.

Place and issue date: Ljubljana, 25. 05. 2020



Dr.-Ing. Miro Uran, General Manager





Certifikat skladnosti s SIST EN ISO 3834-2:2006

Priloga

Obseg veljavnosti certifikata z ozn. 2042-3834-782-20

Produktni standard(i):

SIST EN 1090-2:2018

Alternativni standard(i) (v povezavi s SIST EN ISO 3834-5:2015):

**Načini varjenja
(SIST EN ISO 4063:2011)**

135
141

**Skupine osnovnih materialov
(SIST-TP CEN ISO/TR 15608:2017)**

1.1; 1.2
1.1; 1.2


Osebe za koordinacijo varilskih del:

Ime in priimek	Kvalifikacija	Funkcija in stopnja*
Duško Hlebec	IWE	Welding coordinator – comprehensive

*Stopnja mora biti navedena skladno s SIST EN ISO 14731:2007.

Dr.-Ing. Miro Uran, univ.dipl.inž.

General Manager



INSTITUT ZA VARILSTVO
Welding Institute